

Power Mix Fast

High-quality, protective coating for concrete, wood & steel structures (without primer)

Description: -

Power Mix Fast is a high-quality one-component fast dry protective paint based on premium modified alkyd resins.

Power Mix Fast is a protective coating for steel structures, wood, and concrete without primer.

Usage: -

- Used for wood surfaces against weather conditions.
- Used as an anti-rust protective coating for steel structures.
- Used for concrete protection.
- Used for new & old surfaces after their preparation.
- Preferred to fast drying application.

Advantages: -

- One component fast dry top coat paint.
- Easy to apply and use, whether with a spray gun, roller, or brush.
- High adhesion strength on different surfaces.

- Available in multiple attractive colors or custom colors upon request.
- Attractive smooth finish.
- High durability and Color Stability.
- High hiding power & good coverage rate.
- High weather resistance.

Characteristics: At 25°

color	Customized
Density kg/liter	1.25 ± 0.05
Initial setting time	20 : 25 min
Final setting time	24 hours
Re-coating time	4 : 6 hours
Rate of use	7 : 9 m ² / kg (50 microns)
Thinner	Power solve 4
Gloss	Semigloss

Note: Use rate depends on substrate, thickness, application & surface preparation.

Dilution Rate:

10 to 20% of the product's weight. (Depends on application technique)

Application Tools:

Roller, brush, spray gun.

Application instructions: -

- The substrate must be cleaned well, and free from dust, oils, grease, and friable particles and rust must be removed in the case of metal surfaces.

- Sand the old paint surfaces well to remove any rust, if present, and then clean the surface.
- Stir the product before application to obtain optimal finish.
- Apply one or more primer coats as needed of Power Primer to obtain the perfect finish, our Power products are recommended.
- Apply the paint according to standard procedures, using a brush or roller, painting horizontally and vertically while ensuring complete coverage of the surface to be painted or sprayed.
- Apply the second coat if needed after 4 : 6 hours.
- Typically, two coats of Power Fast are applied, ensuring the first coat is completely dry.
- If necessary, thin the product with Power Solve 4.

Safety precautions: -

- The product should be applied in a well-ventilated area.
- Gloves, protective clothing, and eye goggles should be worn during application.
- Never eat, drink, or smoke during application.
- In case of skin contamination, wash the contaminated area with water and soap.
- In case of eye contamination, immediately wash with abundant lukewarm water and consult a doctor immediately.
- Avoid spilling residues of the product into any watercourse or soil.
- The used tools should be washed immediately after completion with the cleaning solvent Power Solve 1.
- Dispose of product residues or empty containers according to local environmental regulations.

Packages: -

1 kit in volume [Gallon 4 kg].

[Pail 20 kg].

[Drum 200 Kg].

Storage: -

The product should be stored for two years in tightly sealed containers and under appropriate storage conditions.

For more information or inquiries, Visit our website.

Power-cp.net

Disclaimer: The technical data provided herein is accurate and correct as of the publication date and is subject to change without prior notice. The information in this datasheet is not exhaustive. Application conditions should comply with those mentioned in this datasheet. The company is not responsible for any losses resulting from application under differing conditions.

Edition: 7/2024

